Page 1 of 1

# UNITED STATES PATENT AND TRADEMARK OFFICE

# CERTIFICATE OF CORRECTION

PATENT NO.

: 6,669,821 B2

: December 30, 2003

DATED

INVENTOR(S) : Steven L. Edwards et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### Column 22,

Line 63, after "a transfer cylinder", insert -- , wherein said nascent web is located between said foraminous endless fabric and said transfer cylinder --.

#### Column 23,

Line 19, after "a transfer cylinder", insert --, wherein said nascent web is located between said foraminous endless fabric and said transfer cylinder --.

## Column 24,

Lines 33 and 56, after "a backing roll", insert --, wherein said nascent web is located between said foraminous endless fabric and said backing roll --. Lines 38, 39-40, 41, 60, 61-62 and 63, "transfer cylinder" should read -- backing roll --.

#### Column 25,

Line 55, after "a transfer cylinder", insert --, wherein said nascent web is located between said foraminous endless fabric and said transfer cylinder --.

# Column 26,

Line 11, after "a transfer cylinder", insert --, wherein said nascent web is located between said foraminous endless fabric and said transfer cylinder --. Lines 39 and 61, after "a backing roll", insert --, wherein said nascent web is located between said foraminous endless fabric and said backing roll --. Lines 43, 44-45, 46, 66 and 67, "transfer cylinder" should read -- backing roll --.

#### Column 27,

Lines 1 and 2, "transfer cylinder" should read -- backing roll --.

Signed and Sealed this

Eighth Day of June, 2004

JON W. DUDAS Acting Director of the United States Patent and Trademark Office